



**P/N 93150 / 93151**

## **Small Block Chevy Oil Pan Gasket**

Due to the fact that these gaskets will be used on engine blocks made by different manufacturers some slight modifications may be required. The area around the dipstick tube may not clear some aftermarket blocks, if the tube does not line up with dipstick tube you can trim the metal core / silicone rubber to allow proper fitment. Some blocks have cast cavities on the opposite side of the dipstick hole that will need to be filled with silicone RTV gasket material to prevent a leak around the gasket cutout. It is recommended that a small amount of silicone sealant is used in the corners where the front timing cover mates to the block and where the rear main cap mates to the block.

**For Technical Assistance, Call Moroso's Tech Line at  
(203) 458-0542, 458-0546 8:30am – 5:00pm Eastern Time**

**MOROSO PERFORMANCE PRODUCTS, INC**  
**80 CARTER DR • GUILFORD, CT 06437**  
*Phone: (203) 453-6571 • Fax: (203) 453-6906*

**Visit Us At [www.moroso.com](http://www.moroso.com)**

93150/93151inst

Rev A  
061412