



INSTALLATION INSTRUCTIONS P/N 23970 – INSPECTION PLUG

It is recommended that this kit be installed on the non-kickout side of the oil pan. The steel weld-in fitting should be located approximately 2" down from the pan rail and in line with a connecting rod assembly that is convenient to look at when the pan is installed in the car.

NOTE: The weld-in fitting has tapered threads and can only be installed one way. Be sure the fitting does not extend into the oil pan too far where it may interfere with the rotating crankshaft.

The aluminum fitting should be coated with a never seize lubricant to prevent galling of the threads.

PARTS LIST

- (1) Oil Heater Fitting Seal (1) Plug, 1" NPT, Aluminum

***For Technical Assistance, Call Moroso's Tech Line at
(203) 458-0542, 458-0546 8:30am – 5:00pm Eastern Time***

MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906

Visit Us At www.moroso.com